



Capability & Price List

Engine Type : V2500 D5

Airfoil Services Sdn Bhd
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor Darul Ehsan
Malaysia
Tel No: +6 03 61453600

Workscope	Repair No	Description	Additional Info	Repair Type
<u>ATA Chapter: 72-50-32</u>		<u>LPT Blade Stage 3</u>		
3A2055, 3A2373				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	4204	Blend Repair the KES	-	OEM
	4206	Blend Repair the Shroud Notch Radius Crack	-	OEM
	4298	Touch-Up Coating	-	OEM
	4300	Strip and Recoat the Aluminide Coating	-	OEM
	4306	Restore Shroud Pre-Twist	-	OEM
	4509	Blend Repair for Surface Damage	-	OEM
	4511	Restore Shroud Pre-Twist	-	OEM
Full Repair	4204	Blend Repair the KES	-	OEM
	4288	Weld Build-Up of Outer Shroud Hardface	-	OEM
	4297	Weld Build-Up of KES	-	OEM
	4298	Touch-Up Coating	-	OEM
	4300	Strip and Recoat the Aluminide Coating	-	OEM
	4306	Restore Shroud Pre-Twist	-	OEM
	4509	Blend Repair for Surface Damage	-	OEM
	4510	Weld Build-Up of KES	-	OEM
	4511	Restore Shroud Pre-Twist	-	OEM
	4512	Weld Build-Up of Outer Shroud Hardface	-	OEM
	<u>ATA Chapter: 72-50-32</u>		<u>LPT Blade Stage 4</u>	
3A1804, 3A2374, 3A2923				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	4537	Blend Repair for Surface Damage	-	OEM
	4292	Blend Repair for Surface Damage	-	OEM
	4294	Touch-Up Coating	-	OEM
	4296	Strip and Recoat the Aluminide Coating	-	OEM
	4301	Blend Repair the KES	-	OEM
	4305	Restore Shroud Pre-Twist	-	OEM
	4345	Blend Repair the Shroud Notch Radius Crack	-	OEM
	4539	Restore Shroud Pre-Twist	-	OEM
Full Repair	4287	Weld Build-Up of Outer Shroud Hardface	-	OEM
	4292	Blend Repair for Surface Damage	-	OEM
	4293	Weld Build-Up of KES	-	OEM
	4294	Touch-Up Coating	-	OEM
	4296	Strip and Recoat the Aluminide Coating	-	OEM
	4301	Blend Repair the KES	-	OEM
	4305	Restore Shroud Pre-Twist	-	OEM
	4345	Blend Repair the Shroud Notch Radius Crack	-	OEM
	4519	Weld Build-Up of KES	-	OEM
	4537	Blend Repair for Surface Damage	-	OEM
	4538	Weld Build-Up of KES	-	OEM
	4539	Restore Shroud Pre-Twist	-	OEM
	4540	Weld Build-Up of Outer Shroud Hardface	-	OEM



Capability & Price List

Engine Type : V2500 D5

Airfoil Services Sdn Bhd
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor Darul Ehsan
Malaysia
Tel No: +6 03 61453600

Workscope	Repair No	Description	Additional Info	Repair Type
<u>ATA Chapter: 72-50-32</u>		<u>LPT Blade Stage 5</u>		
3A1805, 3A2475				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	4191	Blend Repair for Surface Damage	-	OEM
	4192	Blend Repair the KES	-	OEM
	4193	Blend Repair the Shroud Notch Radius Crack	-	OEM
	4304	Restore Shroud Pre-Twist	-	OEM
Full Repair	4191	Blend Repair for Surface Damage	-	OEM
	4192	Blend Repair the KES	-	OEM
	4193	Blend Repair the Shroud Notch Radius Crack	-	OEM
	4286	Weld Build-Up of Outer Shroud Hardface	-	OEM
	4291	Weld Build-Up of KES	-	OEM
	4304	Restore Shroud Pre-Twist	-	OEM
	4440	Weld Build-Up of KES	-	OEM
<u>ATA Chapter: 72-50-32</u>		<u>LPT Blade Stage 6</u>		
3A1806, 3A2704				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	4185	Blend Repair for Surface Damage	-	OEM
	4186	Blend Repair the KES	-	OEM
	4187	Blend Repair the Shroud Notch Radius Crack	-	OEM
	4303	Restore Shroud Pre-Twist	-	OEM
Full Repair	4185	Blend Repair for Surface Damage	-	OEM
	4186	Blend Repair the KES	-	OEM
	4187	Blend Repair the Shroud Notch Radius Crack	-	OEM
	4285	Weld Build-Up of Outer Shroud Hardface	-	OEM
	4290	Weld Build-Up of KES	-	OEM
	4303	Restore Shroud Pre-Twist	-	OEM
	4560	Weld Build-Up of KES	-	OEM
<u>ATA Chapter: 72-50-32</u>		<u>LPT Blade Stage 7</u>		
3A1807, 3A2477				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	4179	Blend Repair for Surface Damage	-	OEM
	4180	Blend Repair the KES	-	OEM
	4181	Blend Repair the Shroud Notch Radius Crack	-	OEM
	4302	Restore Shroud Pre-Twist	-	OEM
Full Repair	4179	Blend Repair for Surface Damage	-	OEM
	4180	Blend Repair the KES	-	OEM
	4181	Blend Repair the Shroud Notch Radius Crack	-	OEM
	4284	Weld Build-Up of Outer Shroud Hardface	-	OEM
	4289	Weld Build-Up of KES	-	OEM
	4302	Restore Shroud Pre-Twist	-	OEM
	4439	Weld Build-Up of KES	-	OEM