



# Capability & Price List

**Airfoil Services Sdn Bhd**  
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi  
Taman Sains Selangor 1  
Kota Damansara PJU5  
47810 Petaling Jaya  
Selangor Darul Ehsan  
Malaysia  
Tel No: +6 03 61453600

Engine Type : CF6-80C2

Workscope	Repair No	Description	Additional Info	Repair Type
<b>ATA Chapter: 72-31-02</b>		<b>HPC Blade Stage 2</b>		
K212P03, K212P04, K215P01, K215P02				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Standard Repair</b>	001	Blend Repair	-	OEM
	002	Glass Bead Peen Repair	-	OEM
	003	Repair of Copper-Nickel-Indium Coating on Dovetail	-	OEM
	004	Blend Airfoil Tip Erosion	-	OEM
	005	Tip Weld Buildup	-	OEM
	006	Shotpeen Repair Of The Dovetails	-	OEM
	007	Repair of Dovetail Room Temperature Vulcanizing (RTV) Sealant	-	OEM
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 3</b>		
K643P17, K643P18, K643P19, K643P20, K643P21, K643P22, K643P23, K643P24				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Standard Repair</b>	001	Blade Tip Repair in Area D	-	OEM
	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	013	Repair of Aluminum Bronze Coating on Improved Geometry Dovetails, Stages 3-5 Only	-	OEM
	014	Tip Weld Buildup	-	OEM
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 4</b>		
K644P13, K644P14, K644P15, K644P16, K644P17, K644P18, K644P19, K644P20, K644P21, K644P22, K644P23, K644P24				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Standard Repair</b>	001	Blade Tip Repair in Area D	-	OEM
	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	013	Repair of Aluminum Bronze Coating on Improved Geometry Dovetails, Stages 3-5 Only	-	OEM
	014	Tip Weld Buildup	-	OEM
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 5</b>		
K645P13, K645P14, K645P15, K645P16, K645P17, K645P18, K645P19, K645P20, K645P21, K645P22, K645P23, K645P24				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Standard Repair</b>	001	Blade Tip Repair in Area D	-	OEM
	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	013	Repair of Aluminum Bronze Coating on Improved Geometry Dovetails, Stages 3-5 Only	-	OEM
	014	Tip Weld Buildup	-	OEM



# Capability & Price List

**Airfoil Services Sdn Bhd**  
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi  
Taman Sains Selangor 1  
Kota Damansara PJU5  
47810 Petaling Jaya  
Selangor Darul Ehsan  
Malaysia  
Tel No: +6 03 61453600

Engine Type : CF6-80C2

Workscope	Repair No	Description	Additional Info	Repair Type
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 6</b>		
K615P01, K615P02, K615P03, K615P04, K615P05, K615P06, K615P07, K615P08, K615P09, K615P10, K615P11, K615P12, K616P05, K615P13, K615P14, K615P15, K615P16, K616P06, K616P07, K616P08, K616P09, K616P10, K616P11, K616P12				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Standard Repair</b>	001	Blade Tip Repair in Area D	-	OEM
	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	004	Repair of Copper-Nickel-Indium Coated Dovetail	-	OEM
	005	Repair of Replacement of Dovetail Solid Film Lubricant	-	OEM
	006	Shotpeen Repair Of The Dovetails	-	OEM
	009	Tip Weld Buildup	-	OEM
<b>Extended Repair - CWR</b>	012	Chord Restoration	-	OEM
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 7</b>		
K657P04, K657P05, K657P06, K657P07, K657P08, K715P05, K715P06, K715P07, K715P08, K715P09, K715P10, K715P11, K715P12, K715P13, K715P14, K715P15, K715P16, K717P05, K717P08, K715P17, K715P18, K715P19, K715P20, K717P06, K717P07, K657P01, K657P02, K657P03				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Standard Repair</b>	001	Blade Tip Repair in Area D	-	OEM
	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	004	Repair of Copper-Nickel-Indium Coated Dovetail	-	OEM
	005	Repair of Replacement of Dovetail Solid Film Lubricant	-	OEM
	006	Shotpeen Repair Of The Dovetails	-	OEM
	009	Tip Weld Buildup	-	OEM
<b>Extended Repair - CWR</b>	012	Chord Restoration	-	OEM
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 8</b>		
K658P05, K658P06, K658P07, K658P08, K818P05, K818P06, K818P07, K818P08, K818P09, K818P13, K818P14, K818P15, K818P16, K818P10, K818P11, K818P12, K818P17, K818P18, K818P19, K818P20, K658P01, K658P02, K658P03, K658P04				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Standard Repair</b>	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	004	Repair of Copper-Nickel-Indium Coated Dovetail	-	OEM
	005	Repair of Replacement of Dovetail Solid Film Lubricant	-	OEM
	006	Shotpeen Repair Of The Dovetails	-	OEM
	009	Tip Weld Buildup	-	OEM
	<b>Extended Repair - CWR</b>	012	Chord Restoration	-
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 9</b>		
K919P05, K919P06, K919P07, K919P08, K919P09, K919P10, K919P11, K919P12, K919P13, K919P14, K919P15, K919P16, K919P17, K919P18, K919P19, K919P20				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Standard Repair</b>	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	004	Repair of Copper-Nickel-Indium Coated Dovetail	-	OEM
	005	Repair of Replacement of Dovetail Solid Film Lubricant	-	OEM
	006	Shotpeen Repair Of The Dovetails	-	OEM
	009	Tip Weld Buildup	-	OEM
	<b>Extended Repair - CWR</b>	012	Chord Restoration	-



# Capability & Price List

**Airfoil Services Sdn Bhd**  
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi  
Taman Sains Selangor 1  
Kota Damansara PJU5  
47810 Petaling Jaya  
Selangor Darul Ehsan  
Malaysia  
Tel No: +6 03 61453600

Engine Type : CF6-80C2

Workscope	Repair No	Description	Additional Info	Repair Type
<b>ATA Chapter: 72-31-03 HPC Blade Stage 10</b>				
K088P07, K088P08, K088P10, K090P01, K090P02, K090P03, K090P04, K090P05, K090P06, K090P07, K090P08, K090P09, K090P10, K090P12, K090P13, K090P14, K090P15, K090P16, K088P09, K090P11				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Standard Repair	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	006	Shotpeen Repair Of The Dovetails	-	OEM
	009	Tip Weld Buildup	-	OEM
Extended Repair - CWR	012	Chord Restoration	-	OEM
<b>ATA Chapter: 72-31-03 HPC Blade Stage 11</b>				
K188P19, K188P22, K190P01, K190P02, K190P03, K190P04, K190P05, K190P08, K190P09, K190P10, K190P11, K190P12, K188P21, K190P13, K190P14, K190P15, K190P16, K188P16, K188P17, K188P18, K188P20, K190P06, K190P07				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Standard Repair	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	006	Shotpeen Repair Of The Dovetails	-	OEM
	009	Tip Weld Buildup	-	OEM
Extended Repair - CWR	012	Chord Restoration	-	OEM
<b>ATA Chapter: 72-31-03 HPC Blade Stage 12</b>				
K289P07, K289P08, K289P09, K289P10, K289P11, K289P15, K289P16, K289P17, K289P18, K289P12, K289P14, K289P13				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Standard Repair	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	006	Shotpeen Repair Of The Dovetails	-	OEM
	009	Tip Weld Buildup	-	OEM
Extended Repair - CWR	012	Chord Restoration	-	OEM
<b>ATA Chapter: 72-31-03 HPC Blade Stage 13</b>				
K388P11, K388P12, K388P13, K388P14, K388P15, K388P16, K388P17, K388P18				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Standard Repair	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	006	Shotpeen Repair Of The Dovetails	-	OEM
<b>ATA Chapter: 72-31-03 HPC Blade Stage 14</b>				
K488P07, K488P08, K488P09, K488P10, K488P11, K488P12, K488P13, K488P14				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Standard Repair	002	Blend Repair	-	OEM
	003	Glass Bead Peen Repair	-	OEM
	006	Shotpeen Repair Of The Dovetails	-	OEM
	009	Tip Weld Buildup	-	OEM
Extended Repair - CWR	012	Chord Restoration	-	OEM