

Capability & Price List

Engine Type: CFM56-5A

Airfoil Services Sdn Bhd Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi Taman Sains Selangor 1 Kota Damansara PJU5

47810 Petaling Jaya Selangor Darul Ehsan Malaysia

Tel No: +6 03 61453600

Workscope	Repair No	Description	Additional Info	Repair Type
ATA Chapter: 72-54-01	LPT	F Blade Stage 1	_	
336-003-504-0, 336-003-506-				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	002	Airfoil Blend Repair	-	OEM
9	003	Resetting of Pre-twist angle	-	OEM
	009	Corrosion Removal on LPT Blades Root by Blending		OEM
Full Repair	002	Airfoil Blend Repair	-	OEM
	003	Resetting of Pre-twist angle	-	OEM
	005	Recondition of Seal Teeth with CM64	-	OEM
	007	Recondition of Hard Face/Mate Face with CM64 and Radii with Inconel 625	-	OEM
	009	Corrosion Removal on LPT Blades Root by Blending		OEM
Extended Repair 1	006	Recondition of Aluminide Coating (No Touch-up)		OEM
Extended Repair 2	004	Recondition of Plasma Spray Seal Teeth	-	OEM
Extended Repair 3	055	Overcoating of the SVPA Protection on the LPT Blades		OEM
ATA Chapter: 72-54-02	<u>LPT</u>	FBlade Stage 2		
336-003-604-0, 336-003-605	-0, 336-003-608-0, 3	36-003-612-0, 336-003-650-0, 336-003-610-0		
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Airfoil Blend Repair	-	OEM
	003	Resetting of Pre-twist angle	-	OEM
	010	Corrosion Removal on LPT Blades Root by Blending		OEM
	028	Molten Salt	-	OEM
Full Repair	001	Airfoil Blend Repair	-	OEM
	003	Resetting of Pre-twist angle	-	OEM
	004	Recondition of Seal Teeth with CM64	-	OEM
	005	Recondition of Hard Face/Mate Face with CM64 and Radii with Inconel 625	-	OEM
	010	Corrosion Removal on LPT Blades Root by Blending		OEM
	028	Molten Salt	-	OEM
Extended Repair 1	002	Recondition of Plasma Spray Seal Teeth	-	OEM
ATA Chapter: 72-54-02	<u>LPT</u>	F <u>Blade Stage 3</u>		
336-003-702-0, 336-003-703	-0, 336-003-706-0, 3	36-003-708-0		
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Airfoil Blend Repair	-	OEM
	003	Resetting of Pre-twist angle	-	OEM
	011	Corrosion Removal on LPT Blades Root by Blending		OEM
	028	Molten Salt	-	OEM
Full Repair	001	Airfoil Blend Repair	-	OEM
	003	Resetting of Pre-twist angle	-	OEM
	004	Recondition of Seal Teeth with CM64	-	OEM
	006	Recondition of Hard Face/Mate Face with CM64 and Radii with Inconel 625	-	OEM
	011	Corrosion Removal on LPT Blades Root by Blending		OEM
	028	Molten Salt	-	OEM
Extended Repair 1	002	Recondition of Plasma Spray Seal Teeth	-	OEM
	302	resonation of Fluorita Opticy Court Fourt	-	JEW -



Capability & Price List

Engine Type : CFM56-5A

Airfoil Services Sdn Bhd

Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi Taman Sains Selangor 1 Kota Damansara PJU5 47810 Petaling Jaya Selangor Darul Ehsan Malaysia

Tel	No:	+6	03	614	53600	
-----	-----	----	----	-----	-------	--

Workscope	Repair No	Description	Additional Info	Repair Type
ATA Chapter: 72-54-02	<u>LPT</u>	Blade Stage 4		
336-003-802-0, 336-003-803	3-0, 336-003-821-0, 33	86-003-822-0		
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Airfoil Blend Repair	-	OEM
	003	Resetting of Pre-twist angle	-	OEM
	028	Molten Salt	-	OEM
Full Repair	001	Airfoil Blend Repair	-	OEM
	003	Resetting of Pre-twist angle	-	OEM
	004	Recondition of Seal Teeth with CM64	-	OEM
	007	Recondition of Hard Face/Mate Face with CM64 and Radii with Inconel 625	-	OEM
	008	Recondition of Hard Face/Mate Face with T800 and Radii with Inconel 625	-	OEM
	009	Recondition of Hard Face with T800 from RBD 191	-	OEM
	028	Molten Salt	-	OEM