



Capability & Price List

Airfoil Services Sdn Bhd
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor Darul Ehsan
Malaysia
Tel No: +6 03 61453600

Engine Type : V2500 Select One

Workscope	Repair No	Description	Additional Info	Repair Type
ATA Chapter: 72-41-15		HPC Blade Stage 4		
6A8738				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	6010	Repair Damage By Material Removal	-	OEM
	6066	Vibro Polish To Restore The Surface Finish	-	OEM
	6150(EM19VG272)	Restore The Airfoil Surface Condition By Ceramic Bead Peening	-	OEM
	6214	Replace The Seal Strip	-	OEM
	6486	Restore The Anti-Fret Treatment	-	OEM
Extended Repair 1	SH TO 72-41-15 039	Tip Welding of HPC Blades Stages 4 to 12	OEM Equivalent Repair	DER
ATA Chapter: 72-41-15		HPC Blade Stage 5		
6B1346				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	6011	Repair Damage By Material Removal	-	OEM
	6067	Vibro Polish To Restore The Surface Finish	-	OEM
	6150(EM19VG272)	Restore The Airfoil Surface Condition By Ceramic Bead Peening	-	OEM
	6215	Replace The Seal Strip	-	OEM
	6486	Restore The Anti-Fret Treatment	-	OEM
Extended Repair 1	SH TO 72-41-15 039	Tip Welding of HPC Blades Stages 4 to 12	OEM Equivalent Repair	DER
ATA Chapter: 72-41-15		HPC Blade Stage 6		
6A8732, 6A8733, 6A8797, 6A8798, 6B1494				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	6012	Repair Damage By Material Removal	-	OEM
	6068	Vibro Polish To Restore The Surface Finish	-	OEM
	6150(EM19VG272)	Restore The Airfoil Surface Condition By Ceramic Bead Peening	-	OEM
	6495	Restore The Anti-Fret Treatment	-	OEM
	Extended Repair 1	SH TO 72-41-15 039	Tip Welding of HPC Blades Stages 4 to 12	OEM Equivalent Repair
ATA Chapter: 72-41-15		HPC Blade Stage 7		
6A8741, 6A8742, 6A8743, 6A8744, 6B1495				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	6013	Repair Damage By Material Removal	-	OEM
	6069	Vibro Polish To Restore The Surface Finish	-	OEM
	6150(EM19VG272)	Restore The Airfoil Surface Condition By Ceramic Bead Peening	-	OEM
	6496	Restore The Anti-Fret Treatment	-	OEM
	Extended Repair 1	SH TO 72-41-15 039	Tip Welding of HPC Blades Stages 4 to 12	OEM Equivalent Repair



Capability & Price List

Airfoil Services Sdn Bhd
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor Darul Ehsan
Malaysia
Tel No: +6 03 61453600

Engine Type : V2500 Select One

Workscope	Repair No	Description	Additional Info	Repair Type
ATA Chapter: 72-41-15		HPC Blade Stage 8		
6A8745, 6A8746, 6A8747, 6A8748, 6B1496				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	6014	Repair Damage By Material Removal	-	OEM
	6070	Vibro Polish To Restore The Surface Finish	-	OEM
	6150(EM19VG272)	Restore The Airfoil Surface Condition By Ceramic Bead Peening	-	OEM
	6497	Restore The Anti-Fret Treatment	-	OEM
Extended Repair 1	SH TO 72-41-15 039	Tip Welding of HPC Blades Stages 4 to 12	OEM Equivalent Repair	DER
ATA Chapter: 72-41-15		HPC Blade Stage 9		
6A8749, 6A8750, 6A8751, 6A8752				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	6015	Repair Damage By Material Removal	-	OEM
	6071	Vibro Polish To Restore The Surface Finish	-	OEM
	6150(EM19VG272)	Restore The Airfoil Surface Condition By Ceramic Bead Peening	-	OEM
	6497	Restore The Anti-Fret Treatment	-	OEM
Extended Repair 1	SH TO 72-41-15 039	Tip Welding of HPC Blades Stages 4 to 12	OEM Equivalent Repair	DER
ATA Chapter: 72-41-15		HPC Blade Stage 10		
6A8753, 6A8754, 6A8755, 6A8756				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	6016	Repair Damage By Material Removal	-	OEM
	6072	Vibro Polish To Restore The Surface Finish	-	OEM
	6150(EM19VG272)	Restore The Airfoil Surface Condition By Ceramic Bead Peening	-	OEM
	6497	Restore The Anti-Fret Treatment	-	OEM
Extended Repair 1	SH TO 72-41-15 039	Tip Welding of HPC Blades Stages 4 to 12	OEM Equivalent Repair	DER
ATA Chapter: 72-41-15		HPC Blade Stage 11		
6A8757, 6A8758, 6A8759, 6A8760				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	6017	Repair Damage By Material Removal	-	OEM
	6073	Vibro Polish To Restore The Surface Finish	-	OEM
	6150(EM19VG272)	Restore The Airfoil Surface Condition By Ceramic Bead Peening	-	OEM
	6497	Restore The Anti-Fret Treatment	-	OEM
Extended Repair 1	SH TO 72-41-15 039	Tip Welding of HPC Blades Stages 4 to 12	OEM Equivalent Repair	DER
ATA Chapter: 72-41-15		HPC Blade Stage 12		
6A8761, 6A8762, 6A8763, 6A8764				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	6018	Repair Damage By Material Removal	-	OEM
	6074	Vibro Polish To Restore The Surface Finish	-	OEM
	6150(EM19VG272)	Restore The Airfoil Surface Condition By Ceramic Bead Peening	-	OEM
	6497	Restore The Anti-Fret Treatment	-	OEM
Extended Repair 1	SH TO 72-41-15 039	Tip Welding of HPC Blades Stages 4 to 12	OEM Equivalent Repair	DER