



# Capability & Price List

**Airfoil Services Sdn Bhd**  
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi  
Taman Sains Selangor 1  
Kota Damansara PJU5  
47810 Petaling Jaya  
Selangor Darul Ehsan  
Malaysia  
Tel No: +6 03 61453600

Engine Type : V2500 Select One

Workscope	Repair No	Description	Additional Info	Repair Type
<u>ATA Chapter: 72-41-32</u>		<u>HPC Vane Stage 3</u>		
6A8720, 6B1271, 6B1273, 6A8721, 6B1272				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	6034	Repair Surface Damage By Material Removal	-	OEM
	6076	Vibro Polish To Restore The Surface Finish	-	OEM
<u>ATA Chapter: 72-41-32</u>		<u>HPC Vane Stage 4</u>		
6A8731, 6B1274, 6B1275				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	6035	Repair Surface Damage By Material Removal	-	OEM
	6077	Vibro Polish To Restore The Surface Finish	-	OEM
	6183	Repair Worn/Damaged Inner And/or Outer Pivot Journal By Metal Spray	-	OEM
<u>ATA Chapter: 72-41-32</u>		<u>HPC Vane Stage 5</u>		
6A8725, 6B1277, 6A8728, 6B1276				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	6036	Repair Surface Damage By Material Removal	-	OEM
	6078	Vibro Polish To Restore The Surface Finish	-	OEM
	6184	Repair Worn/Damaged Inner And/or Outer Pivot Journal By Metal Spray	-	OEM
<u>ATA Chapter: 72-41-22</u>		<u>HPC Vane Stage 6</u>		
6A8767, 6A8766, 6A8765				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	6210	Ceramic Bead Peen To Restore The Airfoil Surface Condition	-	OEM
	6503	Repair The Airfoil By Material Removal	-	OEM
	6499	Vibro Polish To Restore The Surface Finish	-	OEM
Extended Repair 1	SH TO 72-41-22 012	Tip Welding of HPC Vanes	OEM Equivalent Repair	DER
<u>ATA Chapter: 72-41-22</u>		<u>HPC Vane Stage 7</u>		
6A8769, 6A8768, 6A8770				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	6025	Repair The Airfoil By Material Removal	-	OEM
	6080	Vibro Polish To Restore The Surface Finish	-	OEM
	6210	Ceramic Bead Peen To Restore The Airfoil Surface Condition	-	OEM
Extended Repair 1	SH TO 72-41-22 012	Tip Welding of HPC Vanes	OEM Equivalent Repair	DER
<u>ATA Chapter: 72-41-22</u>		<u>HPC Vane Stage 8</u>		
6A8774, 6A8775, 6A8772, 6A8776, 6A8773				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	6026	Repair The Airfoil By Material Removal	-	OEM
	6081	Vibro Polish To Restore The Surface Finish	-	OEM
	6210	Ceramic Bead Peen To Restore The Airfoil Surface Condition	-	OEM
Extended Repair 1	SH TO 72-41-22 012	Tip Welding of HPC Vanes	OEM Equivalent Repair	DER



# Capability & Price List

**Airfoil Services Sdn Bhd**  
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi  
Taman Sains Selangor 1  
Kota Damansara PJU5  
47810 Petaling Jaya  
Selangor Darul Ehsan  
Malaysia  
Tel No: +6 03 61453600

Engine Type : V2500 Select One

Workscope	Repair No	Description	Additional Info	Repair Type
<u>ATA Chapter: 72-41-22</u>		<u>HPC Vane Stage 9</u>		
6A8782, 6A8781, 6A8780, 6A8779, 6A8778				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	6027	Repair The Airfoil By Material Removal	-	OEM
	6082	Vibro Polish To Restore The Surface Finish	-	OEM
	6210	Ceramic Bead Peen To Restore The Airfoil Surface Condition	-	OEM
Extended Repair 1	SH TO 72-41-22 012	Tip Welding of HPC Vanes	OEM Equivalent Repair	DER
<u>ATA Chapter: 72-41-22</u>		<u>HPC Vane Stage 10</u>		
6A8783, 6A8785, 6A8786, 6A8784				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	6028	Repair The Airfoil By Material Removal	-	OEM
	6083	Vibro Polish To Restore The Surface Finish	-	OEM
	6210	Ceramic Bead Peen To Restore The Airfoil Surface Condition	-	OEM
Extended Repair 1	SH TO 72-41-22 012	Tip Welding of HPC Vanes	OEM Equivalent Repair	DER
<u>ATA Chapter: 72-41-22</u>		<u>HPC Vane Stage 11</u>		
6A8789, 6A8790, 6A8791, 6A8788, 6A8787				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	6029	Repair The Airfoil By Material Removal	-	OEM
	6084	Vibro Polish To Restore The Surface Finish	-	OEM
	6210	Ceramic Bead Peen To Restore The Airfoil Surface Condition	-	OEM
Extended Repair 1	SH TO 72-41-22 012	Tip Welding of HPC Vanes	OEM Equivalent Repair	DER
<u>ATA Chapter: 72-41-32</u>		<u>HPC Vane Stage IGV</u>		
6B1269, 6B1270				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	6033	Blend Repair	-	OEM
	6075	Restore The Surface Finish	-	OEM