



Transport
Canada

Transports
Canada

This letter replaces letter issued on May 23, 2019

Transport Canada Civil Aviation
Standards Branch (AART)
330 Sparks Street
Ottawa, ON, Canada
K1A 0N5

Company File: 5015-19034
RDIMS: 15334324v2

Date: June 11, 2019

Mr. Eric Lee Chan Wai
Airfoil Services Sdn Bhd
No.12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor
Malaysia

Subject: Authorization of FAA-certificated Repair Stations located outside the United States

Dear Mr. Eric Lee Chan Wai,

This letter authorizes **Airfoil Services Sdn Bhd** Certification No. **A6FY344J** to perform maintenance and modifications on aeronautical products, excluding aircraft, under TCCA regulatory control pursuant to Section B, Paragraph 4.0, of the FAA/TCCA Maintenance Implementation Procedures (MIP).

This authorization is limited to **V2500 engines** manufactured by **IAE International Aero Engines**, **CF6-80C2 engines** manufactured by **General Electric**, **CFM56-3/5A/5B/(5B/P)/5C/7B engines** manufactured by **CFM International**, and the work performed must be within the ratings and limitations contained in your 14 CFR Part 145 certificate, operations specifications and applicable capability lists dated prior to **May 23, 2019**. Any changes applied to your certificate, operations specifications, or capability list will invalidate this authorization and a new authorization request will be required by TCCA.

This TCCA authorization shall remain in effect until **Airfoil Services Sdn Bhd** FAA Repair Station Certificate expires **October 31, 2020** or if the Certificate has been surrendered, suspended or revoked. In order to renew this authorization, TCCA requires **Airfoil Services Sdn Bhd** to provide their renewed certificate, and demonstrate compliance with the MIP Section B, Paragraph 4.1, as part of their new authorization request.

Regards,

Marc Pichette

Civil Aviation Safety Inspector
Operational Airworthiness, Standards

