



Capability List

Engine Type: CF6-80C2

Airfoil Services Sdn Bhd
Company No. 228623-U
 GST NO: 00195333248
 No 12, Jalan Teknologi
 Taman Sains Selangor 1
 Kota Damansara PJU5
 47810 Petaling Jaya
 Selangor Darul Ehsan
 Malaysia
 Tel No: +6 03 61453600

Workscope	Repair No	Description	Additional Info	Repair Type
<u>ATA Chapter: 72-32-02</u>				
<u>HPC Vane Stage 1</u>				
K186P04, K461P03				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
<u>ATA Chapter: 72-32-02</u>				
<u>HPC Vane Stage 2</u>				
K286P04, K462P02, K462P01, K232P01				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane		OEM
<u>ATA Chapter: 72-32-02</u>				
<u>HPC Vane Stage 3</u>				
K344P04, K463P02				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
	CINSP2	Cleaning and Inspection		OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	003	Tip Weld Repair		OEM
Light Repair PII	001	Blend Repair Phase II Aero Vane		OEM
Full Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	004	Tip Weld Repair of Phase II Aero Vanes		OEM
<u>ATA Chapter: 72-32-02</u>				
<u>HPC Vane Stage 4</u>				
K445P04, K464P02				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
	CINSP2	Cleaning and Inspection		OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	003	Tip Weld Repair		OEM
Light Repair PII	001	Blend Repair Phase II Aero Vane		OEM
Full Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	004	Tip Weld Repair of Phase II Aero Vanes		OEM
<u>ATA Chapter: 72-32-02</u>				
<u>HPC Vane Stage 5</u>				
K465P03, K575P02, K546P04				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
	CINSP2	Cleaning and Inspection		OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	003	Tip Weld Repair		OEM
Light Repair PII	001	Blend Repair Phase II Aero Vane		OEM
Full Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	004	Tip Weld Repair of Phase II Aero Vanes		OEM



Capability List

Engine Type: CF6-80C2

Airfoil Services Sdn Bhd
Company No. 228623-U
 GST NO: 00195333248
 No 12, Jalan Teknologi
 Taman Sains Selangor 1
 Kota Damansara PJU5
 47810 Petaling Jaya
 Selangor Darul Ehsan
 Malaysia
 Tel No: +6 03 61453600

Workscope	Repair No	Description	Additional Info	Repair Type
ATA Chapter: 72-32-03				
HPC Vane Stage 6				
K466P01, K466P02, K466P03, K466P04, K466P05, K466P06, K600P31, K600P32, K600P34, K600P35, K600P36, K600P45, K600P46, K600P48, K600P49, K600P50, K600P52, K600P38, K236P01, K236P02, K236P03, K236P04, K236P05, K236P06				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
	CINSP2	Cleaning and Inspection		OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	002	Repair of Fixed Vane Dovetail Coating	-	OEM
	003	Tip Weld Repair	-	OEM
Light Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
Full Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
	004	Tip Weld Repair of Phase II Aero Vanes		OEM
ATA Chapter: 72-32-03				
HPC Vane Stage 7				
K467P01, K467P02, K467P03, K467P04, K779P34, K779P35, K779P36, K779P37, K779P62, K779P63, K779P64, K779P65, K779P66, K779P38, K237P01, K237P02, K237P03, K237P04				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
	CINSP2	Cleaning and Inspection		OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	002	Repair of Fixed Vane Dovetail Coating	-	OEM
	003	Tip Weld Repair	-	OEM
Light Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
Full Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
	004	Tip Weld Repair of Phase II Aero Vanes		OEM
ATA Chapter: 72-32-03				
HPC Vane Stage 8				
K468P01, K468P02, K468P03, K468P04, K808P09, K808P11, K808P12, K808P14, K808P15, K808P16, K808P17, K808P18, K808P10, K238P01, K238P02, K238P03, K238P04				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
	CINSP2	Cleaning and Inspection		OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	002	Repair of Fixed Vane Dovetail Coating	-	OEM
	003	Tip Weld Repair	-	OEM
Light Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
Full Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
	004	Tip Weld Repair of Phase II Aero Vanes		OEM



Capability List

Engine Type: CF6-80C2

Airfoil Services Sdn Bhd
Company No. 228623-U
 GST NO: 00195333248
 No 12, Jalan Teknologi
 Taman Sains Selangor 1
 Kota Damansara PJU5
 47810 Petaling Jaya
 Selangor Darul Ehsan
 Malaysia
 Tel No: +6 03 61453600

Workscope	Repair No	Description	Additional Info	Repair Type
ATA Chapter: 72-32-03				
HPC Vane Stage 9				
K239P02, K469P01, K469P02, K469P03, K469P04, K469P05, K469P06, K900P08, K900P09, K900P10, K900P11, K900P12, K900P14, K900P16, K239P01, K239P03, K239P04, K239P05, K239P06				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
	CINSP2	Cleaning and Inspection		OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	002	Repair of Fixed Vane Dovetail Coating	-	OEM
	003	Tip Weld Repair	-	OEM
Light Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
Full Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
	004	Tip Weld Repair of Phase II Aero Vanes		OEM
ATA Chapter: 72-32-03				
HPC Vane Stage 10				
K012P01, K012P02, K012P03, K012P04, K012P05, K012P07, K012P09, K240P03, K240P05, K470P01, K470P02, K470P03, K470P04, K470P05, K470P06, K240P01, K240P02, K240P04, K240P06				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
	CINSP2	Cleaning and Inspection		OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	002	Repair of Fixed Vane Dovetail Coating	-	OEM
	003	Tip Weld Repair	-	OEM
Light Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
Full Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
	004	Tip Weld Repair of Phase II Aero Vanes		OEM
ATA Chapter: 72-32-03				
HPC Vane Stage 11				
K182P36, K182P37, K182P38, K182P41, K182P42, K182P63, K182P64, K182P65, K182P68, K182P69, K182P77, K182P79, K182P80, K182P81, K182P82, K182P83, K182P84, K182P85, K182P86, K241P02, K241P06, K471P01, K471P02, K471P03, K471P04, K471P15, K471P16, K471P17, K471P18, K182P78, K241P01, K241P03, K241P04, K241P05, K241P07, K241P08				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
	CINSP2	Cleaning and Inspection		OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	002	Repair of Fixed Vane Dovetail Coating	-	OEM
	003	Tip Weld Repair	-	OEM
Light Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
Full Repair PII	001	Blend Repair Phase II Aero Vane		OEM
	002	Repair of Fixed Vane Dovetail Coating		OEM
	004	Tip Weld Repair of Phase II Aero Vanes		OEM
Extended Repair 1	SB 72-1118	Stage 11 Vane Slot Inspection and Copper-Nickel-Indium Vanes	-	OEM



Capability List

Engine Type: CF6-80C2

Airfoil Services Sdn Bhd
Company No. 228623-U
GST NO: 00195333248
No 12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor Darul Ehsan
Malaysia
Tel No: +6 03 61453600

Workscope	Repair No	Description	Additional Info	Repair Type
ATA Chapter: 72-32-03				
HPC Vane Stage 12				
K200P12, K200P13, K200P14, K200P15, K200P16, K200P17, K200P18, K242P02, K472P01, K472P02, K472P03, K472P04, K472P05, K472P06, K242P01, K242P03, K242P04, K242P05, K242P06				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
	CINSP2	Cleaning and Inspection	-	OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	002	Repair of Fixed Vane Dovetail Coating	-	OEM
	003	Tip Weld Repair	-	OEM
Light Repair PII	001	Blend Repair Phase II Aero Vane	-	OEM
	002	Repair of Fixed Vane Dovetail Coating	-	OEM
Full Repair PII	001	Blend Repair Phase II Aero Vane	-	OEM
	002	Repair of Fixed Vane Dovetail Coating	-	OEM
	004	Tip Weld Repair of Phase II Aero Vanes	-	OEM
ATA Chapter: 72-32-03				
HPC Vane Stage 13				
K027P01, K027P02, K027P04, K027P05, K027P06, K027P07, K314G04, K314G05				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	002	Repair of Fixed Vane Dovetail Coating	-	OEM
	003	Tip Weld Repair	-	OEM
ATA Chapter: 72-34-19				
HPC Vane Stage 14				
K046P07, K046P08, K047G02, K688P43, K688P45, K688P52, K688P53				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM
	002	Replacement of Spray Coat on OGV Dovetail	-	OEM
ATA Chapter: 72-32-02				
HPC Vane Stage IG V				
K086P04				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	001	Blend Repair Phase I/O Aero Vane	-	OEM