



Capability & Price List

Airfoil Services Sdn Bhd
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor Darul Ehsan
Malaysia
Tel No: +6 03 61453600

Engine Type : CFM56-3

Workscope	Repair No	Description	Additional Info	Repair Type
<u>ATA Chapter: 72-54-01</u>		<u>LPT Blade Stage 1</u>		
301-330-112-0, 301-330-113-0, 301-330-114-0, 301-330-115-0				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Airfoil Blend Repair	-	OEM
	003	Resetting of Pre-Twist Angle	-	OEM
Full Repair	001	Airfoil Blend Repair	-	OEM
	003	Resetting of Pre-Twist Angle	-	OEM
	004	Recondition of Hard Face/Mate Face with CM64 and Radii with Inconel 625	-	OEM
	005	Recondition of Seal Teeth with CM64	-	OEM
Extended Repair 1	002	Recondition of Aluminide Coating (No Touch-Up)	-	OEM
Extended Repair 2	009	Recondition of Plasma Spray Seal Teeth	-	OEM
Extended Repair 3	055	Overcoating of the Vapor Phase Aluminization Protection	-	OEM
<u>ATA Chapter: 72-54-02</u>		<u>LPT Blade Stage 2</u>		
301-330-213-0, 301-330-214-0, 301-330-217-0, 301-330-218-0, 301-330-221-0, 301-330-222-0, 301-330-215-0, 301-330-216-0				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Airfoil Blend Repair	-	OEM
	002	Resetting of Pre-Twist Angle	-	OEM
	018	Molten Salt	-	OEM
Full Repair	001	Airfoil Blend Repair	-	OEM
	002	Resetting of Pre-Twist Angle	-	OEM
	003	Recondition of Hard Face/Mate Face with CM64 and Radii with Inconel 625	-	OEM
	006	Recondition of Seal Teeth with CM64	-	OEM
	008	Recondition (conversion) of Hard Face/Mate Face to CM64 from Originally Hard Faces Manufactured with RBD 191	-	OEM
	018	Molten Salt	-	OEM
	Extended Repair 1	017	Recondition of Plasma Spray Seal Teeth	-
<u>ATA Chapter: 72-54-02</u>		<u>LPT Blade Stage 3</u>		
301-330-317-0, 301-330-320-0, 301-330-321-0, 301-330-322-0, 301-330-325-0, 301-330-326-0, 301-330-315-0, 301-330-316-0, 301-330-319-0				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Airfoil Blend Repair	-	OEM
	002	Resetting of Pre-Twist Angle	-	OEM
	018	Molten Salt	-	OEM
Full Repair	001	Airfoil Blend Repair	-	OEM
	002	Resetting of Pre-Twist Angle	-	OEM
	004	Recondition of Hard Face/Mate Face with CM64 and Radii with Inconel 625	-	OEM
	006	Recondition of Seal Teeth with CM64	-	OEM
	009	Recondition (conversion) of Hard Face/Mate Face to CM64 from Originally Hard Faces Manufactured with RBD 191	-	OEM
	018	Molten Salt	-	OEM
Extended Repair 1	017	Recondition of Plasma Spray Seal Teeth	-	OEM



Capability & Price List

Airfoil Services Sdn Bhd
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi
Taman Sains Selangor 1
Kota Damansara PJU5
47810 Petaling Jaya
Selangor Darul Ehsan
Malaysia
Tel No: +6 03 61453600

Engine Type : CFM56-3

Workscope	Repair No	Description	Additional Info	Repair Type
<u>ATA Chapter: 72-54-02</u>		<u>LPT Blade Stage 4</u>		
301-330-425-0, 301-330-428-0, 301-330-430-0, 301-330-431-0, 301-330-433-0, 301-330-434-0, 301-330-435-0, 301-330-423-0, 301-330-427-0, 301-330-436-0, 301-330-439-0, 301-330-437-0, 301-330-438-0, 301-330-421-0, 301-330-429-0				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Light Repair	001	Airfoil Blend Repair	-	OEM
	002	Resetting of Pre-Twist Angle	-	OEM
	018	Molten Salt	-	OEM
Full Repair	001	Airfoil Blend Repair	-	OEM
	002	Resetting of Pre-Twist Angle	-	OEM
	005	Recondition of Hard Face/Mate Face with CM64 and Radii with Inconel 625	-	OEM
	006	Recondition of Seal Teeth with CM64	-	OEM
	007	Recondition of Hard Face/Mate Face with T800 and Radii with Inconel 625	-	OEM
	010	Recondition (conversion) of Hard Face/Mate Face to T800 from Originally Hard Faces Manufactured with RBD 191 or CM64	-	OEM
	018	Molten Salt	-	OEM