



# Capability & Price List

**Airfoil Services Sdn Bhd**  
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi  
Taman Sains Selangor 1  
Kota Damansara PJU5  
47810 Petaling Jaya  
Selangor Darul Ehsan  
Malaysia  
Tel No: +6 03 61453600

Engine Type : CFM56-5A

Workscope	Repair No	Description	Additional Info	Repair Type
<b>ATA Chapter: 72-31-01</b>		<b>HPC Blade Stage 1</b>		
(2D) P161P03, P161P04, P161P07, P161P08, P161P09, P161P10, P161P11, P191P06, P191P08, P191P09, P191P10				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Full Repair</b>	001	Blending of Blade Tip Leading Edge & Trailing Edge	-	OEM
	002	Repair of Dovetail Wear Coating Cu-Ni-In	-	OEM
	004	Repair of the Short Airfoil Tip Length	-	OEM
	005	Repair of the Dovetail RTV Sealant	-	OEM
	009	Application of HVOF Tungsten Carbide Airfoil Erosion Coating	-	OEM
	010	Repair of Dovetail Wear Coating Al-Br	-	OEM
<b>Extended Repair 1</b>	011	Trailing Edge Fillet/Platform Blend Repair	-	OEM
<b>Extended Repair 2</b>	007	Blend & Contour of Airfoil Leading Edge	-	OEM
<b>ATA Chapter: 72-31-02</b>		<b>HPC Blade Stage 2</b>		
(2D) P122P02, P122P07, P132P03, P132P04, P132P05, P132P10, P132P11, P132P12, P142P02, P142P03, P142P04, P142P05, P102P04				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Full Repair</b>	001	Blending of Blade Tip Leading Edge & Trailing Edge	-	OEM
	002	Repair of Dovetail Wear Coating Cu-Ni-In	-	OEM
	004	Repair of the Short Airfoil Tip Length	-	OEM
	005	Repair of the Dovetail RTV Sealant	-	OEM
	009	Application of HVOF Tungsten Carbide Airfoil Erosion Coating	-	OEM
	010	Repair of Dovetail Wear Coating Al-Br	-	OEM
<b>Extended Repair 1</b>	011	Trailing Edge Fillet/Platform Blend Repair	-	OEM
<b>Extended Repair 2</b>	007	Blend & Contour of Airfoil Leading Edge	-	OEM
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 3</b>		
(2D) P103P03, P103P04, P103P05, P103P09, P103P10, P103P11, P103P13, P103P14, P103P15				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Full Repair</b>	001	Blending of Blade Tip Leading Edge & Trailing Edge	-	OEM
	002	Repair of Dovetail Wear Coating Cu-Ni-In	-	OEM
	004	Repair of the Short Airfoil Tip Length	-	OEM
	005	Repair of the Dovetail RTV Sealant	-	OEM
	009	Application of HVOF Tungsten Carbide Airfoil Erosion Coating	-	OEM
	010	Repair of Dovetail Wear Coating Al-Br	-	OEM
<b>Extended Repair 1</b>	011	Trailing Edge Fillet/Platform Blend Repair	-	OEM
<b>Extended Repair 2</b>	007	Blend & Contour of Airfoil Leading Edge	-	OEM
<b>Extended Repair 3</b>	012 (acc. to RD 050-465-P7)	Chord Restoration and Tip Weld Repair	-	OEM
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 4</b>		
(2D) P104P01, P104P02, P104P03, P104P04, P104P06, P104P07, P104P08, P104P09, P104P10, P104P11, P104P12, P104P13, P104P30, P104P31, P104P32, P104P33, P104P34, P104P35, P104P36, P104P37, P104P38, P104P39, P104P40, P104P41, P104P44, P104P43, P104P45, P104P46, P104P47, P104P48, P104P49, P104P42				
<b>Cleaning &amp; Inspection</b>	C&I	Cleaning & Inspection	-	OEM
<b>Full Repair</b>	001	Blending of Blade Tip Leading Edge & Trailing Edge	-	OEM
	004	Repair of the Short Airfoil Tip Length	-	OEM
	010	Application of HVOF Tungsten Carbide Airfoil Erosion Coating	-	OEM
<b>Extended Repair 1</b>	012 (acc. to RD 050-465-P7)	Chord Restoration and Tip Weld Repair	-	OEM
<b>Extended Repair 2</b>	007	Blend & Contour of Airfoil Leading Edge	-	OEM



# Capability & Price List

**Airfoil Services Sdn Bhd**  
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi  
Taman Sains Selangor 1  
Kota Damansara PJU5  
47810 Petaling Jaya  
Selangor Darul Ehsan  
Malaysia  
Tel No: +6 03 61453600

Engine Type : CFM56-5A

Workscope	Repair No	Description	Additional Info	Repair Type
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 5</b>		
(2D) P105P01, P105P02, P105P03, P105P04, P105P06, P105P07, P105P08, P105P09, P105P10, P105P11, P105P12, P105P13, P105P14, P105P15, P105P16, P105P17, P105P22, P105P23, P105P24, P105P25, P105P34, P105P35, P105P36, P105P37, P105P38, P105P39, P105P40, P105P41, P105P42, P105P43, P105P46, P105P47, P105P48, P105P49, P105P44, P105P45				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	001	Blending of Blade Tip Leading Edge & Trailing Edge	-	OEM
	004	Repair of the Short Airfoil Tip Length	-	OEM
	010	Application of HVOF Tungsten Carbide Airfoil Erosion Coating	-	OEM
Extended Repair 1	012 (acc. to RD 050-465-P7)	Chord Restoration and Tip Weld Repair	-	OEM
Extended Repair 2	007	Blend & Contour of Airfoil Leading Edge	-	OEM
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 6</b>		
(2D) P106P01, P106P02, P106P03, P106P04, P106P06, P106P07, P106P08, P106P09, P106P11, P106P12, P106P13, P106P18, P106P19, P106P20, P106P21, P106P30, P106P31, P106P32, P106P33, P106P34, P106P35, P106P36, P106P37, P106P39, P106P40, P106P41, P106P42, P106P43, P106P44, P106P45, P106P38, P106P10				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	001	Blending of Blade Tip Leading Edge & Trailing Edge	-	OEM
	004	Repair of the Short Airfoil Tip Length	-	OEM
	011	Application of HVOF Chrome Carbide Airfoil Erosion Coating	-	OEM
Extended Repair 1	012 (acc. to RD 050-465-P7)	Chord Restoration and Tip Weld Repair	-	OEM
Extended Repair 2	007	Blend & Contour of Airfoil Leading Edge	-	OEM
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 7</b>		
(2D) P107P01, P107P02, P107P03, P107P04, P107P06, P107P07, P107P08, P107P09, P107P10, P107P11, P107P12, P107P13, P107P18, P107P19, P107P20, P107P21, P107P30, P107P31, P107P32, P107P33, P107P34, P107P35, P107P36, P107P37, P107P38, P107P39, P107P40, P107P41, P107P42, P107P43, P107P44, P107P45				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	001	Blending of Blade Tip Leading Edge & Trailing Edge	-	OEM
	004	Repair of the Short Airfoil Tip Length	-	OEM
	011	Application of HVOF Chrome Carbide Airfoil Erosion Coating	-	OEM
Extended Repair 1	012 (acc. to RD 050-465-P7)	Chord Restoration and Tip Weld Repair	-	OEM
Extended Repair 2	007	Blend & Contour of Airfoil Leading Edge	-	OEM
<b>ATA Chapter: 72-31-03</b>		<b>HPC Blade Stage 8</b>		
(2D) P108P01, P108P02, P108P03, P108P04, P108P06, P108P07, P108P08, P108P09, P108P10, P108P11, P108P12, P108P13, P108P18, P108P19, P108P20, P108P21, P108P30, P108P31, P108P32, P108P33, P108P34, P108P35, P108P36, P108P37, P108P38, P108P39, P108P42, P108P43, P108P44, P108P45, P108P40, P108P41				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	001	Blending of Blade Tip Leading Edge & Trailing Edge	-	OEM
	004	Repair of the Short Airfoil Tip Length	-	OEM
	011	Application of HVOF Chrome Carbide Airfoil Erosion Coating	-	OEM
Extended Repair 1	012 (acc. to RD 050-465-P7)	Chord Restoration and Tip Weld Repair	-	OEM
Extended Repair 2	007	Blend & Contour of Airfoil Leading Edge	-	OEM



# Capability & Price List

**Airfoil Services Sdn Bhd**  
Co. Reg. No.: 199101018312 (228623 U)

No 12, Jalan Teknologi  
Taman Sains Selangor 1  
Kota Damansara PJU5  
47810 Petaling Jaya  
Selangor Darul Ehsan  
Malaysia  
Tel No: +6 03 61453600

Engine Type : CFM56-5A

Workscope	Repair No	Description	Additional Info	Repair Type
<u>ATA Chapter: 72-31-03</u>		<u>HPC Blade Stage 9</u>		
<small>(2D) P109P01, P109P02, P109P03, P109P04, P109P06, P109P07, P109P08, P109P09, P109P10, P109P11, P109P12, P109P13, P109P18, P109P19, P109P20, P109P21, P109P30, P109P31, P109P32, P109P33, P109P34, P109P35, P109P36, P109P37, P109P39, P109P40, P109P41, P109P42, P109P43, P109P44, P109P45, P109P38</small>				
Cleaning & Inspection	C&I	Cleaning & Inspection	-	OEM
Full Repair	001	Blending of Blade Tip Leading Edge & Trailing Edge	-	OEM
	004	Repair of the Short Airfoil Tip Length	-	OEM
	011	Application of HVOF Chrome Carbide Airfoil Erosion Coating	-	OEM
Extended Repair 1	012 (acc. to RD 050-465-P7)	Chord Restoration and Tip Weld Repair	-	OEM
Extended Repair 2	007	Blend & Contour of Airfoil Leading Edge	-	OEM